






EKECBUA*3V
EKECBUA*6V
EKECBUA*9W

EKECBUCO1A*
EKECBUCO2A*
EKECBUCO3A*



EBS*-D / EHS*-E
ELS*-E




1 EKECBUA*



2 EKECBUCO2(3)A*

ETS*12-E
ETS*16-E(7)




1 EKECBUCO1A*





2 EKECBUA*

EKECBUA*		2
EKECBUCO2A*	EBS*-D / ELS*-E	4
EKECBUCO3A*	EHS*-E	4
EKECBUCO1A*	ETS*12-E / ETS*16-E(7)	7


EKECBUA*




EKECBUA*




5x 
≤2 N·m



1.1




1.2







1.3



1.4




1.5







EKECBUCO2(3)A*




EKECBUCO2(3)A*




2.1




2.2



2.3




EKECBUA*




1.1 1.5

EBS*-D / ELS*-E + EKECBUCO2A*



2.4



EHS*-E + EKECBUCO3A*



2.5










EBS*-D / ELS*-E + EKECBUCO2A*

EHS*-E + EKECBUCO3A*



2.6





2.7



2.8



2.9







EKECBUCO2(3)A*


EBS*-D / ELS*-E + EKECBUCO2A*

EHS*-E + EKECBUCO3A*


2.10




EKECBUA*
+
EKECBUCO2A*




EKECBUA*
+
EKECBUCO3A*







EKECBUC01A*




3.1




3.2




3.3




3.4




3.5




3.6



3.7




3.8





EKECBUC01A*

3.9



2-3


1.1

.....


1.5

EKECBUA*


3.10




3.11




3.12




3.13






3.14




3.15




3.16



3.17



EKECBUA*
+
EKECBUC01A*



DAIKIN EUROPE N.V.

Zandvoordestraat 300, B-8400 Oostende, Belgium

4P670270-1E 08/2025